

*Before Pilot Project at Leratong Hospital*



Sharps containers with large hole for direct vertical loading

*During Pilot Project at Leratong Hospital*



Sharps container with horizontal loading via safety sluice



Broken pedal bin for HCRW in sluice room



Wall mounted bin with liner in sluice room

*Before Pilot Project at Leratong Hospital*



Nurse trolley with red bag hanging loose fixed with tape

*During Pilot Project at Leratong Hospital*



Nurse trolley with puncture proof holder for red bag



Large standing bin for domestic waste in corridors etc.



Wall mounted rack with bag for domestic waste etc.

*Before Pilot Project at Leratong Hospital*



140 litre Cardboard box receiving HCRW in the wards

*During Pilot Project at Leratong Hospital*



100 litre puncture proof stackable box for HCW in sluice



Filled 140 litre cardboard box sealed and awaiting collection



Filled thick red liner being removed from stand in sluice

*Before Pilot Project at Leratong Hospital*



Filled sealed HCRW cardboard box awaiting collection in corridor

*During Pilot Project at Leratong Hospital*

No HCRW is left unattended in public places!



Internal collection of cardboard boxes with HCRW



Internal collection of reusable stackable boxes in cage trolley

*Before Pilot Project at Leratong Hospital*



Internal collection of cardboard boxes with HCRW

*During Pilot Project at Leratong Hospital*



Internal collection of thick liners using 770 litre wheelie bin



Manual transfer of non-puncture proof cardboard boxes to truck



Wheeled transfer of stackable boxes using lifting tail gate

*Before Pilot Project at Leratong Hospital*



Manual feeding of non-puncture proof cardboard boxes to incinerator

*During Pilot Project at Leratong Hospital*



Mechanical lifting of wheelie bins into hopper of incinerator



Washing and disinfection of 770 litre wheelie bin



Drying of 770 litre wheelie bin after cleaning